




Agrium CPO - Soda Springs, ID
#2 Belt Filter
10/5/05
P. Boys

Agrium CPO - Soda Springs, ID
Top of WPPA scrubber
10/5/05
P. Boys





Agrium CPO - Soda Springs, ID
Top of WPPA scrubber
10/5/05
P. Boys




Agrium CPO - Soda Springs, ID
WPPA Scrubber Stack
10/5/05
P. Boys



Enclosure Gap
Fugitive Emissions

Agrium CPO - Soda Springs, ID
Pan Filter Enclosure
10/5/05
P. Boys




Enclosure Gap
Fugitive Emissions

Agrium CPO - Soda Springs
Pan Filter Enclosure
10/5/05
P. Boys




Agrium CPO - Soda Springs
Pan Filter Inlet Area
10/5/05
P. Boys



Missing Enclosure Panel


The image shows a large, dark, industrial enclosure, likely a pan filter enclosure, with a missing panel. A yellow safety railing is visible in the foreground. The enclosure is made of dark metal panels, and the missing panel is indicated by a line pointing to the gap. The background shows a corrugated metal roof structure.

Agrium CPO - Soda Springs
Pan Filter Enclosure
10/5/05
P. Boys




Section of Enclosure Panel
Propped Open
(No worker present)

Agrium CPO - Soda Springs, ID
Pan Filter Enclosure
10/5/05
P. Boys



Section of Enclosure Panel
Propped Open
(No worker present)

Agrium CPO - Soda Springs, ID
Pan Filter Enclosure
10/5/05
P. Boys



Gap in Enclosure Panel
Fugitive Emissions Escaping

Agrium CPO - Soda Springs, ID
Pan Filter Enclosure
10/5/05
P. Boys



Agrium CPO - Soda Springs, ID
Top of SPA Scrubber
10/5/05
P. Boys

Agrium CPO - Soda Springs, ID
10/6/05
P. Boys



Agrium CPO - Soda Springs, ID
10/6/05
P. Boys



Agrium CPO - Soda Springs, ID
10/6/05
P. Boys

Gypsum Stack



Welcome to
Agrium
CONDA PHOSPHATE OPERATION
THINK SAFE BE SAFE

1,000,000
SAFE MAN HOURS
1989, 1992, 1995, 1999, 2001

TRUCK
ENTRANCE
←